


Difference in stave profile when cold, and
when cold with 12W of power
(Plot=cold -- cold-with-power)



A second measurement at warm and cold temps...only one line measured along center of stave

